

<b>TABLE 16</b> <b>SOLID WASTE MANAGEMENT UNITS (SWMU*) WITH SUSPECTED RELEASES</b>	
<b>SWMU Number</b>	<b>SWMU Description</b>
1	Demilitarization Area/Disposal Pits
2	Gravel pits (Area 10)
3	Disposal pit (Southeast of Area 2)
4	Mortar pits (Southeast of Area 2)
5	Drainage pond and Leaching pit (next to Building 600) and Building 600
6 <sup>a</sup>	Building 600
7 <sup>a</sup>	Leaching pit (next to Building 600)
8	Surveillance Test Site
9	Area 2 (including mustard holding and pit areas)
10 <sup>b</sup>	Does not meet the definition of a SWMU
11	Chemical Munitions Storage Area (Area 10)
12 <sup>b</sup>	Does not meet the definition of a SWMU
13 <sup>c</sup>	SWMU listed on Table 17
14	Building S-108
15	Old demolition pit (Warehouse C-4200)
16 <sup>b</sup>	Does not meet the definition of a SWMU
17 <sup>c</sup>	SWMU listed on Table 17
18 <sup>d</sup>	SWMU not located at the Facility
19	Building 533
20	Building 521
21	Incendiary washout operations (Building S-554)
22	Incendiary washout basins
23	Demilitarization holding area (North of SWMU #1)
24 <sup>e</sup>	SWMU combined with number 36
25	Demilitarization area/Disposal pits
26	Sanitary landfill (active)
27	Sewage treatment plant
28	Inactive landfill (northeast corner)
29	Metal scrap landfill

<p><b>TABLE 16</b> <b>SOLID WASTE MANAGEMENT UNITS (SWMU*) WITH SUSPECTED RELEASES</b></p>	
<b>SWMU Number</b>	<b>SWMU Description</b>
30	Chemical Agent Munition Disposal System landfill
31	Demilitarization area (North of SWMU #1)
32	Railroad scrap yard
33	Building 536
34	Building 4105
35 <sup>f</sup>	Building 533
36	Building 3200 and surrounding area
a	For the purposes of the corrective action under this permit, SWMU 6 and 7 have been combined with SWMU 5.
b	Currently does not meet the definition of a Solid Waste Management Unit.
c	SWMU with known-release(s), listed in Table 17.
d	SWMU 18 is not included because it is located within Tooele-North.
e	SWMU 24 is located in SWMU 36.
f	SWMU 35 is the same unit as SWMU 19.
*	The SWMU numbering corresponds to that used in Ground-water Consultation No. 38-26-1364-86, September 5, 1986, conducted by the U.S. Army Environmental Hygiene Agency and the RCRA Facility Assessment, December 1987, prepared for EPA.